

## **Chemical Report**

Hanson Cement Ketton Stamford PE9 3SX Tel: 0330 123 2074 Fax: 01780 727008

Composition of Ribblesdale PC, EN 197-1:2011, CEM I 52,5N Dispatched from Ribblesdale Chemical analysis for week ending 11-Sep-22

Week No. 2022-36

Compound	%
SiO <sub>2</sub>	21.64
Al <sub>2</sub> O <sub>3</sub>	5.17
Fe <sub>2</sub> O <sub>3</sub>	2.61
CaO	65.00
MgO	2.70
SO <sub>3</sub>	3.45
K <sub>2</sub> O	0.68
Na <sub>2</sub> O	0.23
CI	0.06
Loss on Ignition	2.92
Not Detected	-4.47
Total	104.47

	%
Insol Residue	0.70
Free CaO	1.0
Certified Average Alkali Na <sub>2</sub> O (Equiv)	0.68
LSF (x 100)	91.37

Clinker compounds by Rietveld analysis		
C₃S	53.6	
C <sub>2</sub> S	21.9	
C <sub>3</sub> A	5.4	
C <sub>4</sub> AF	6.6	

For and on behalf of HANSON CEMENT

Cerdial 1

Dr Nina Cardinal, Dipl.Ing., CEng, MiMMM National Technical Manager Hanson Cement Hanson Cement has used all reasonable care to ensure the information herein contained is accurate but to the extent permitted in law, no liability can be accepted by Hanson Cement for any loss, damage, cost or expense arising from any inaccuracy, whether due to negligence or otherwise.

Registered Office: Hanson House, 14 Castle Hill, Maidenhead, Berkshire, SL6 4JJ Registered in England No. 2182762